




Khi Series

Designer Cai Yanzhu , Guan Manru , Ye Hanyi

Materials 15mm plybamboo


Tools CNC engraving machine

Units mm




Upated 2021/11/22
Guangdong University of Technology
Opendesign Workshop

Contents




Khi X

1-5



Khi X mini

6-10





Khi O

11-15

Khi X

SEAT LEGS



15mm plybamboo



Khi X

TABLE TOP


15mm plybamboo



Khi X

ASSEMBLY




No screws, no glue, no tools



Khi X



ASSEMBLY

No screws, no glue, no tools



Khi X ASSEMBLY



No screws, no glue, no tools



Khi X mini

SEAT LEGS



15mm plybamboo



Khi X mini




TABLE TOP

15mm plybamboo






Khi X mini ASSEMBLY

No screws, no glue, no tools





Khi X mini ASSEMBLY

No screws, no glue, no tools



Khi X mini ASSEMBLY



No screws, no glue, no tools



Khi O

SEAT LEGS



15mm plybamboo



Khi O

SEAT TOP

15mm plybamboo




Khi O


ASSEMBLY

No screws, no glue, no tools


A x2



B x2






C



Khi O

ASSEMBLY



No screws, no glue, no tools



Khi O

ASSEMBLY

No screws, no glue, no tools





Guangdong University of Technology

OpenDesign+DIY workshop

2021/11/22